# SOUTH PRODUCTION NOTES

November 13, 2014
Day Shift

BASF EMPLOYEES
36 Last Recordable
502 Last Lost Time

#### #1 MED / Al-4190:

Extruder gear box out of oil -WOW to look at gear box- Engineer does not want extra bags on the floor so only make bags to keep up with Calciner. 5 on the floor is ok. We are ok to run as soon as the Calciner is giving us pink material and surface area are good.

Midnight shift: Did not run.

Day shift:

Afternoon shift:

#### #1 RC / SI-1624:

Only feeding the refired material until we get lab results from the dried material on the floor. Do not feed any of the new dried material until instructed.

Currently exhausted to Trimer because stage 3 is reading Low, Keep an eye on

Currently exhausted to Trimer because stage 3 is reading Low. Keep an eye on #4.

Midnight Shift: Continued with the refire material. Surface area is good, but still getting white material off.

Day shift:

Afternoon shift: Continued.

#### **Exhaust to Trimer**

#### #2 MED line / Cu-0860:

Ready To go. Using small chiller. New unit not working.

Midnight shift: Ran a batch and then put on hold. Unable to drop powder from the control room. Also the weigh hopper vibrator is not working. W.O.W.

Day Shift:

Afternoon Shift:

# #2 RC/ Cu 0860:

On Hold waiting for Extruder

Midnight shift: Hold.

**Day Shift:** 

**Afternoon Shift:** 

#### **Exhaust to F1**

CONFIDENTIAL BASE 114 017955

## #3 MED/ D-1708:

Running- Only on Midnight and Day shift.

Midnight shift: Continued to run.

**Day Shift:** 

**Afternoon Shift: Hold** 

#### #3 RC / D-1795:

Sand run through on afternoon shift, WOW for Cutter, Needs Cleaning finished Midnight shift: Sand continued to trickle through. Hopper on 2<sup>nd</sup> floor needs cleaned. Also calciner side door at a minimum.

Day shift:

Afternoon Shift: Cleaning / Sand

**Exhaust to CTO** 

### #4 RC / D-5253:

Continue to run.

Watch Suction on Trimer, #1 is also venting to Trimer

Midnight Shift: Continued to run.

**Day Shift:** 

**Afternoon Shift:** 

**Exhaust to Trimer** 

### #5 RC / Cu-3818:

Continue.

Keep an eye on the discharge end to make sure there is good suction and is not backing up.

FEED ON LY PHIBROTECH COPPER CARB MATERIALS. DO NOT TAKE ANY WORLD METALS COPPER CARB FROM SHIPPING.

Midnight Shift: Continued.

Day shift:

Afternoon shift:

**Exhaust to 5A DC** 

## <u>6 Tank /D-5253</u>

Keep tank in recycle. NO STEAM. Will need a tank made on 11-13 if possible hold for Rory, he would like to observe the process

Midnight Shift: Monitored.

Day Shift: ok Afternoon shift:

## New Pfaudler / D 5253

Continue on feed to National. Drum set up for drainage- see revised batch

sheet.

Midnight shift: Did not run.(Manpower and pipeline full).

Day shift:

**Afternoon Shift: Continued** 

### 7 Tank AMT

No activity yet. Tank will not be needed until late December...will try to get

cleaning instructions soon.

Midnight Shift: NA
Day Shift: NA

Afternoon shift: NA

## Old Pfaudler / D-0756:

**Making Batches** 

Midnight Shift: Continued.

Day Shift:

**Afternoon shift:** 

## National Dryer: D-5253

Continue. Use blue totes to empty Pfaudler, and ONLY use one buggy for

feeding the National Dryer.

Midnight Shift: Continued to feed.

Day shift:

**Afternoon Shift: Continued** 

### PK Blender/Pill mix reblends:

Pill mix re-blends. Cannot locate material for re-blends

Midnight Shift: Day shift: NA

Afternoon shift: NA

### **Abbe Blender / 5206** Done

Done for a while. Area Cleaned and Contractors finished with Sprinkler work

Afternoon Shift: NA Midnight shift: NA Day shift: NA

## #6 RC / D-0756

Running - no issues

Midnight shift: Continued.

Day Shift:

Afternoon shift: running

**Exhaust to Sly Scrubber** 

### **Tower 3/ DPT 101:**

Continue. Should be ready to unload on day shift 11-12-14

Midnight Shift: Loaded and running.

Day shift:

Afternoon shift:

## **Tower 6 / DPT 101**

Repaired. Continue

Midnight Shift: Loaded and running.

Day shift:

Afternoon shift: running

### North Screener / Cu 0860:

Continue to run.

Midnight shift: On hold for Cu 0860.

Day shift: on hold for 0860

Afternoon shift: on hold for 0860

### **South Screener / DPT 101:**

Continue to run. Gray drums are in building 24.

Midnight shift: Continued to run.

Day shift:

**Afternoon Shift: continue** 

# #2662 (west) Pill Machine / Al-3915 T 5/32:

Midnight shift: Did not run(manpower).

Day Shift:

Afternoon shift: running

# #2664 (east) Pill Machine / Al-3915 T 5/32:

Continue

Midnight shift: Did not run(manpower).

Day shift:

Afternoon shift: running

## TK #2 / V 2010 P :

BI mill is running – Finish Drums left- Then clean and Maintenance to replace

leaking seals.

Midnight shift: Running.

Day Shift:

Afternoon shift:

## TK #4 / Cu 0540:

Temps down.

Midnight shift: Kiln shut off.

Day Shift: Down Afternoon shift:

## <u>Harrop Kiln / Al-4190:</u>

Continue to load and unload and assist screener operator. Using lot 270.

Midnight shift: Continued.

Day Shift:

Afternoon shift:

## **Building 27 Belt Filter / Cu 6081:**

NOTE: new bags are suppose to be ordered for the leaking issues, and will be in soon. Until then Wash off bags and use spray glue to seal for transport to bldg. 24 south east area, and place in bag order. Please fill bags to 1200# and ensure bags are clean of powder on the outside of them and the pallets as they have to be transported down the street.

Midnight shift: On hold on midnight shift.

Day shift:

**Afternoon Shift:** 

#### **Priorities:**

These items should all be considered urgent will require call outs for maintenance issues and/or processing issues.

- 1) #3 MED/#3RC/CTO
- 2) West Pfaudler/National Dryer#4RC/Trimer
- 3) Reduction Towers
- 4) Reduction Tower Screeners
- 5) #1 Line
- 6) Milling V-2046 P
- 7) #2 Tunnel Kiln
- 8) #5 RC
- 9) #2 Line/#2RC
- 10) East Pfaudler/HC-11 Dryer/#6 RC Clean for D-0756
- 11) Horne Tabletting
- 12) South Precip
- 13) Tunnel Kiln Area Touch up paint on Cu-0860 ERL green drums

HI Priority clean ups: 1. #3 Calciner